



PS500

Quick Operation Guide



Switch On



Switch Off



OFF 3





OFF 2

OFF 1

Backlight On

Max

Min



Reset

Confidence Signal

Every



Manual Datalog




Pump




Alarm Indicators





Gas Alarm Acknowledge




Self Test



Flow Fault




Zero Fault



Calibration Overdue



Battery Life



Charging

